Intel New Mexico Community Environmental Working Group August 2008 EHS Activity Report

PLANT STATUS:

Production equipment servicing Fab 11X was operating at approximately 99% of capacity.

MONITORING UNDERWAY OR COMPLETED THIS MONTH:

The Q3'08 VOC testing program for the thermal oxidizers will begin with the F11x Fab thermal oxidizer that will be tested 8/15/08 through 8/29/08 and conclude with the F11x Bridge thermal oxidizer that is scheduled to be tested 9/3/08 through 9/17/08.

INSPECTIONS/MEETINGS:

Meeting with Albuquerque Bernalillo County Water Utility Authority to discuss current operational health of the POTW.

SITE EVENTS:

Date:	Event:	Status/Community Impact:
		Unit down due to programmable logic controller timer
July 6 – 9	Fab 11X Bridge Thermal Oxidizer	
	Downtime	counter issue. Unit went down a second time and
		technicians kept the unit down to perform a detail
		investigation to identify the cause which was found to
		be a punctured rubber boot. Unit down for 82.1 hours.
		VOC emissions – 136.2 lbs.
July 24 – 30	Crane east of Fab 11	Work on Munters units.
July 28 – 30, August 1	Site irrigation testing	Water visible during testing.
-2, August $4 - 10$,		
August 7 – 8		
July 28 – August 8	Irrigation work	Contractors will be working on the irrigation system in
		the parking lot on the south west corner of the site.
August 4 – 10	Weed control application	Spray application of weed control to landscaping
		across site. Application of ant granules sitewide.
August 4 – 15	Fitness trail repair	Concrete along fitness trail along west end of site
		(adjacent to 528) will be repaired.
August 5	Crane near transformers	Repair damaged transformer.
August 5 – 6	Fire pump testing	Water may be seen during testing.
August 7	Rio Rancho Fire Department Training	Trucks will be on site to review site layout.
August 9 – 10	Fab 11X Bridge Thermal Oxidizer	Unit down due to a variable frequency drive fault in the
	Downtime	concentrator for 2.1 hours.
		VOC emissions – 3.5 lbs.
August 14 – 15	Crane west of Fab 7	Work on cooling towers.

INFORMATION REQUESTED BY OR PROVIDED TO REGULATORY AGENCIES:

INFORMATION REQUESTED BY OR FROVIDED TO REGULATORY AGENCIES:		
Item:	Permit or Regulatory Requirement/ Regulatory	
	Request:	
F11X Bridge Thermal Oxidizer Downtime	Permit Requirement	
Quarterly VOC Test Report	Permit Requirement	
Semi Annual Wastewater Report	Permit Requirement	
Semi Annual Sampling Report	Regulatory Requirement	
Annual HAPs Test Report	Permit Requirement	
Radiation Device Registration	Regulatory Requirement	
Quarterly Air Emissions Report	Permit Requirement	
Air Permit Administrative Revision – Correction to Methanol EF	Regulatory Requirement	

Intel New Mexico Community Environmental Working Group August 2008 EHS Activity Report

CALLS RECEIVED: NUMBER OF NEIGHBORS CALLING IN - 3

Comment	Action Taken
July 29 Neighbor in Zone 2 with odor	There was no abatement equipment down, no emergency generators being run and
complaint	no testing of the boiler diesel fuel delivery system during the time of the complaint.
	There were no incidents with the water treatment systems in the CUB or with the
	cooling towers. The only additional activity is the installation of one of the new
	Munters units which requires the use of a crane; however, this activity is being
	performed during the daytime hours of 07:00 and 16:00 hours. The wind direction
	was predominantly out of the north and a bit to the east of north.
August 11 Neighbor in Zone 2 called	No action required.
pleased with the decrease in noise	
levels from Intel and with Intel's	
efforts to continue to decrease noise	
levels	
August 11 Neighbor in Zone 2 called	No action required.
pleased with Intel's success this	
summer in decreasing noise levels and	
with successfully water retention on	
East Slope in heavy rains on the	
weekend.	